



Port 1




Drill all ports #50  
Plug where shown  
with X

Port 4



Port 2



Port 3

